

# ***Supplement to Recommended Practice SNT-TC-1A (Q&A Book): Liquid Penetrant Testing Method, second edition***

## **Text Corrections**

---

The following text correction applies to the first printing of *ASNT Supplement to Recommended Practice SNT-TC-1A (Q&A Book): Liquid Penetrant Testing Method, second edition*. Subsequent printings of the document will incorporate the corrections into the published text.

The answers to the following questions should be corrected as follows:

### **Level I**

- |   |               |
|---|---------------|
| 23. The reference is <u>A.50</u> .      | 54. <u>a</u>  |
| 29. The reference is <u>A.51-52</u> .   | 58. <u>d</u>  |
| 35. The reference is <u>A.171-172</u> . | 61. <u>c</u>  |
| 36. The reference is <u>A.171-172</u> . | 107. <u>a</u> |
| 48. <u>a</u>                            |               |

### **Level II**

- 2. c The reference is A.85.
- 20. c
- 21. d
- 27. d
- 28. c
- 34. c The references are A.129 and C.550.
- 36. b
- 37. d The references are A.128 and B.63.
- 38. b The reference is C.86.
- 49. a
- 51. d The reference is A.47-48.

**Page 22:** The answers to question 42 should be changed to read:

- 42. Which of the following is a discontinuity that might be found in rolled plate stock?
  - a. inclusions
  - b. ~~shrinkage cracks~~ laminations
  - c. forging laps
  - d. blow holes

The answer remains b.

### **Level III**

- 10. d
- 49. c

Catalog #2029  
First book printing 01/11  
Text Corrections printed 09/12